

Appendix H

Storage Tank Closure Documents
208-236 North Beaver Street



Diamond State Environmental, Inc.

R.D.#2 Box 228
Shippensburg, PA 17257
(717) 532-6202

March 5, 1990

York Bank and Trust co.
107 West Market Street
York, Pa. 17401

Subject: Property
Weaver's Auto Body
216 North Beaver Street
York, Pa. 17401

Dear Blair,

In regard to our recent telephone conversation concerning the removal of underground storage tanks at the Weaver property. This letter is to confirm that on May 6, 1987, Diamond State Environmental, Inc. did remove (5) 20,000 gallon storage tanks, (2) 550 gallon tanks, (1) 1,000 gallon tank and filled (1) 15,000 gallon storage tank with sand. This was done in accordance with the State Police Fire Marshall Code, which at that time required, "Any tanks not in use must be filled or removed." Mr. Weaver chose to have his tanks removed.

This letter is only to confirm that the above work was completed by Diamond State Environmental, Inc.

If we may be of any further assistance concerning this matter, you may contact us at (717) 532-6202.

Sincerely,

Joseph B. Hazzard, Sr.

Joseph B. Hazzard, Sr.

JBH/emh

DIAMOND STATE ENVIRONMENTAL, INC.

(302) 878-0264

(717) 532-6202

Proposal

5/5/87


Weaver's Auto Body
216 North Beaver Street
York, PA 17403

Diamond State Environmental, Inc. proposes to perform the following:

1. Remove five 20,000 gallon storage tanks.
2. Remove two 350 gallon storage tanks.
3. Remove one 1,000 gallon storage tank.
4. Fill one 15,000 gallon storage tank.
5. Remove vent and product line where possible.
6. Back fill.
7. Remove plate form and pump in rear of property.
8. Haul tanks away.
9. Back fill will be obtained by owner but paid for from this bid, not to exceed \$5,100.00.
10. Owner will have tanks pumped dry.

Total cost including sales tax: \$15,200.00.

Sincerely,




Joseph D. Hazzard, Field Representative
Diamond State Environmental, Inc.

6-8-87
Paid in full

Signing of this Proposal Constitutes an Agreement Subject to Terms and Conditions on Reverse Side.

Handwritten signature: Weaver's Auto Body J.D. Hazzard

- BARB PLEASE PUT THIS IN OUR FILE
- THANK, TRACEY KRAFT



**ENVIRO LAB, INC.**

Analytical Services for Water • Wastewater • Industry • Agriculture

1221 HANOVER RD. • YORK, PA 17404-6289

PHONE (717) 228-5586

Weaver's Auto Body
Attn: Bill Kraft
215 N. Beaver St.
York, Pa 17403

03-12-90
LABORATORY ANALYSIS REPORT

SAMPLE NAME: Soil Samples #1, #2, #3
DATE SAMPLED: 03-08-90
COLLECTED BY: Client

Parameter	Result	Limit of Detection
Total Petroleum Hydrocarbons in soil #1 (dry weight basis)	< 6 ppm	6 ppm
Total Petroleum Hydrocarbons in soil #2 (dry weight basis)	< 6 ppm	6 ppm
Total Petroleum Hydrocarbons in soil #3 (dry weight basis)	< 6 ppm	6 ppm

Method: SW846-3540/EPA 418.1

Respectfully submitted,

ENVIRO-LAB, INC.

Reviewed and approved by:

Robert L. Weaver
Director